

MSDS No 026-11910-915

REV 02 - Date: August 10, 2012

## USG Middle East Ltd.

## SECTION 1 CHEMICAL PRODUCT AND IDENTIFICATION

PRODUCT: MINERAL FIBER TILES - ACOUSTONE, AURATONE & SONATONE

Olympia II Ceramic Radar Clean Room
Olympia II Micro Mars Clima Plus Eclipse
Fissured Taiga Hygiene Glacier
Europa Plain Pedestals
Radar Perforated Sandrift

Omni Chessboard Sonatone White - Sparta

Aurora Comet Line Sonatone II
Favia Acoustic Halcyon Designer Series

**SYNONYM:** Acoustical Ceiling Tiles and Panels

COMPANY: USG Middle East Ltd PRODUCT SAFETY

7410 Al Kharj Road Ph: AUS 1800 757 943 / NZ 0800 874 496 Second Industrial City Web: www.usg.com.au / www.usg.co.nz

Dammam 34326 – 4201, Kingdom of Saudi Arabia **Tel:** +966 3 812 0995 / **Fax:** +966 3 812 1029

E-mail: info@usgme.com

## SECTION 2 COMPOSITION, INFORMATION ON INGREDIENTS

Ceiling panels are composed of inorganic substances including MMVF22 [(slag wool) man made vitreous (silicate) fibres (CAS 65997-17-3)] and/or MMVF34 [(stone wool) Roxul® 1000 (HT) mineral fibres], expanded perlite (CAS 93763-70-3), clay (kaolin, CAS 1332-58-7), and recycle paper (CAS 9004-34-6) using starch (CAS 9005-25-8) binder to form a solid dry matrix. The ceiling panels are coated on the surface with a solvent-free water based latex paint.

## SECTION 3 HAZARD IDENTIFICATION

#### **EMERGENCY OVERVIEW**

This product is not expected to produce any unusual hazards during normal use. Exposure to high dust levels may irritate the skin, eyes, nose, throat, or upper respiratory tract.

Man-made mineral fibres have been classified by the European Union as irritating to skin.

#### **Label Information**

Man made vitreous (silicate) fibers, nota Q of Directive 97/69/EEC

#### **ACUTE:**

**Eyes:** Airborne dust or direct contact can cause mechanical irritation of eyes. Contact lenses should not be worn when working in dust. If burning, redness, itching, pain or other symptoms persist or develop, consult physician.

**Skin:** Skin contact is not a chemical hazard. Mechanical action of fibers on skin can cause itchiness. If skin contact occurs, do not rub or scratch. Irritation of skin may occur with prolonged and repeated contact. Rinse with cool water, followed by washing with soap and warm water. A commercially available skin cream or lotion may be helpful to treat dry or irritated skin areas.

**Inhalation:** No chronic harmful effects expected. No specific recommendation. If gastric disturbance occurs, call physician

**Ingestion:** Unlikely to occur, but may cause gastric disturbances if swallowed. Gypsum is non-toxic; however, ingestion of a sufficient quantity could lead to mechanical obstruction of the gut, especially the pyloric region. See First Aid Measures - Ingestion (Section 4).

# SF

### **Mineral Fiber Ceiling Tiles**

MSDS No 026-11910-915

REV 02 – Date: August 10, 2012

## **USG Middle East Ltd.**

#### **CHRONIC:**

Inhalation: Slag wool fiber has been classified as "not classifiable as to its carcinogenicity to humans" (Group 3) by the International Agency for Research on Cancer (IARC). (See Section 11) Prolonged and repeated exposure to airborne free respirable crystalline silica can result in lung disease (i.e., silicosis) and/or lung cancer. The development of silicosis may increase the risks of additional health effects. The risk of developing silicosis is dependent upon the exposure intensity and duration. The concentration of respirable crystalline silica measured in airborne dust samples was below the detection limit using NIOSH Method 7500 in industrial hygiene testing of workers installing USG Acoustical Ceiling Panels

for an 8 hour work day. **Eyes:** None known.

Skin: Prolonged and repeated contact with the skin can cause temporary irritation and itchiness. If irritation

persists, consult a physician. None known.

Ingestion: No known effects.

TARGET ORGANS: Eyes, skin and respiratory system.

PRIMARY ROUTES OF ENTRY: Inhalation, eyes and skin contact.

Label Information

Classification: The product is not classified as hazardous under Chemicals Hazardous Information and Packaging for

Supply (CHIPS 2000).

## SECTION 4 FIRST AID MEASURES

#### **FIRST AID PROCEDURES**

**Eyes:** In case of contact, immediately flush thoroughly with copious amounts of water for 15 minutes, occasionally lifting the lower and upper lids (to remove particulates that may scratch the eye). Do not rub eyes. If irritation persists, consult physician.

**Skin:** Wash with mild soap and water. A commercially available hand lotion may be used to treat dry skin areas. If skin has become cracked, take appropriate action to prevent infection and promote healing. If irritation persists, consult physician.

**Inhalation:** Remove to fresh air. Leave the area of dust exposure and remain away until coughing and other symptoms subside. Other measures are usually not necessary, however if conditions warrant, contact physician.

**Ingestion:** No harmful effects expected. No specific recommendations. This product is not intended to be ingested or eaten. If gastric disturbance occurs, call physician.

## SECTION 5 FIRE FIGHTING MEASURES

General Fire Hazards: Not expected to burn.

**Extinguishing Media:** Water or use extinguishing media appropriate for surrounding fire. **Special Fire Fighting Procedures:** Wear appropriate personal protective equipment (See section 8).

Unusual Fire and Explosion Hazards: None

Hazardous Combustion Products:Organic material in panels can produce oxides of carbon. None knownFlash Point:None KnownAuto Ignition:Not ApplicableMethod Used:Not ApplicableFlammabilityLimited combustible

Upper Flammable Limit (UFL): Not Applicable Classification:

Lower Flammable Limit (LFL): Not Applicable Rate of Burning: Not Applicable

## SECTION 6 ACCIDENTAL RELEASE MEASURES

MSDS No 026-11910-915

REV 02 - Date: August 10, 2012

## **USG Middle East Ltd.**

#### **CONTAINMENT PROCEDURES:**

No special precautions. Containment not necessary. Treat as inert material. Keep the spill dry and away from incompatibles (See Section 10). Wear appropriate personal protection (See Section 8). Collect the material from spillage and if not damaged or contaminated by foreign material, ceiling panels may be reclaimed. No special precautions. Wear appropriate personal protective equipment. See section 8.

#### **CLEAN-UP PROCEDURES:**

Use normal clean up procedures. Pick up large pieces. Wear appropriate protective equipment. Use gloves to avoid skin irritation. If dry, shovel or sweep up material from spillage and place collected material into a container for recovery or waste disposal. Avoid dust generation. Avoid inhalation of dust and contact with eyes and skin. Maintain proper ventilation. If vacuum is used to collect dust, use an industrial vacuum cleaner with a high efficiency air filter. If sweeping is necessary, use dust suppressant such as water. Do not dry sweep dust accumulation or use compressed air for clean up. These procedures will help minimize potential exposures.

#### **EVACUATION PROCEDURES:**

Not typically necessary.

#### **SPECIAL INSTRUCTIONS:**

None.

## SECTION 7 HANDLING AND STORAGE

#### **HANDLING:**

Avoid dust contact with eyes. Wear the appropriate eye protection against dust (See Section 8).

Minimize dust generation and accumulation. Avoid breathing dust. Wear the appropriate respiratory protection against dust in poorly ventilated areas and if TLV is exceeded (see Sections 2 and 8). Use good safety and industrial hygiene practices.

Follow traditional building practices; such as management of water away form the interior of the structure to avoid the growth of mold, mildew and fungus. Remove from the jobsite any building products suspected of being exposed to

#### STORAGE:

Warehouse storage should be in accordance with package directions.

Store in a cool, dry, ventilated area away from sources of heat, moisture and incompatibilities (see Section 10). Protect from weather and prevent exposure to sustained moisture. Protect product from physical damage. Warehouse storage should be in accordance with package directions.

## SECTION 8 EXPOSURE CONTROLS / PERSONAL PROTECTION

#### **Exposure Guidelines**

#### A. General Product Information

No exposure limits are assigned to this mixture, see Section 2 - Information on Ingredients. If cutting or trimming with power equipment dust collectors and local ventilation must be used. Wear the appropriate personal protective equipment (see below) if airborne contaminant levels exceed the recommended exposure limits.

#### **B.** Component Exposure Limits


Recommended maximum exposure limit (MEL) is 1 fibre/cc (respirable) and/or 5 mg/m<sub>3</sub> (respirable dust), 8 hour TWA. Refer to current edition of HSE (Health and Safety Executive) EH40 "Occupational Exposure Limits".

Ventilate to keep exposures below recommended level. Good general ventilation is expected to be satisfactory to control airborne levels. Use local exhaust ventilation if necessary to control air contaminants.

#### **ENGINEERING CONTROLS:**

#### Eye/Face

Wear eye protection (safety glasses or goggles) to avoid particulate irritation of the eye.





## **Mineral Fiber Ceiling Tiles**

MATERIAL SAFETY DATA SHEET

REV 02 - Date: August 10, 2012

## JSG Middle East Ltd.

#### Skin

Gloves or protective clothing are usually not necessary but may be desirable in specific work situations. For brief contact, no precautions other than clean body-covering clothing should be needed. Wear gloves and protective clothing to prevent repeated or prolonged skin contact. Wear adequate clothing to minimize chafing or drying of skin. Wear long sleeved, long legged, loose fitting clothing closed at the neck and wrists and minimize skin contact. Wash work clothing separately from other clothing. Rinse washer thoroughly after use.

#### Respiratory

Not typically necessary under normal conditions of use. Avoid creating dust. Use ventilation adequate to keep dust exposures below recommended exposure limits. Wear a dust respirator (mask) or disposable face masks complying with EN149FFP1 or FFP2 in poorly ventilated areas, if recommended exposure limit is exceeded, and/or when dusty conditions exist.

#### General

Selection of Personal Protective Equipment will depend on environmental working conditions and operations.

### **SECTION 9** PHYSICAL AND CHEMICAL PROPERTIES

Appearance	Surface with color; baseboard beige/gray	Odor	Low to no odor
Physical State	Solid	pH @ 25 ° C	~ 9
Vapor Pressure	Not Applicable	Vapor Density (Air = 1)	Not Applicable
<b>Boiling Point</b>	Not Applicable	Vapor Pressure (mm Hg)	Not Applicable
Freezing Point	Not Applicable	Evaporation Rate (BuAc = 1)	Not Applicable
Melting Point	1200°C	Percent Volatile	0
Softening Point	700°C	Particle Size	Not Applicable
Solubility (H2O)	Low	Molecular Weight	Not Applicable
Viscosity	Not Applicable	Bulk Density	250 - 400 kg/m <sub>3</sub>
Specific Gravity (H	• •	•	J

### **SECTION 10 CHEMICAL STABILITY AND REACTIVITY**

STABILITY: Stable in dry environments. CONDITIONS TO AVOID: Contact with incompatibles.

INCOMPATIBILITY: Acids. HAZARDOUS POLYMERIZATION: Will not occur. HAZARDOUS DECOMPOSITION: None known.

### **SECTION 11 TOXICOLOGICAL INFORMATION**

#### **ACUTE EFFECTS:**

#### Acute/Toxicity/Target Organ Information

#### A. General Product/Component Information

This material (in wet state or as dust) is not chemically harmful if it gets on the skin and is not immediately washed off. However direct contact of dust and especially mineral wool fibers with skin can cause skin irritation (mechanical) and itchiness.

## **MATERIAL SAFETY DATA SHEET**

MSDS No 026-11910-915

REV 02 - Date: August 10, 2012

## **Mineral Fiber Ceiling Tiles** JSG Middle East Ltd.

#### CHRONIC EFFECTS / CARCINOGENICITY:

In animal studies, if long stone wool fibers are very durable and present in high concentrations they may lead to disease. Short-term inhalation studies of rats exposed to high levels of stone wool fibers have shown that the long fibers disappear guickly from the lungs (are biodegradable). The new stone wool fibers (MMVF34) are much more biosoluble and will disappear even more rapidly than the traditional types.

Large morbidity and mortality studies of both European and North American mineral wool manufacturing workers have been conducted. These studies have found no significant association of non-malignant (i.e., fibrosis) or malignant (i.e., lung cancer or mesothelioma) lung disease and exposures to slag wool fibers and have not established a causal relationship between exposure to stone wool and malignant diseases.

The synthetic mineral fibers used in these products come from both the United States and Europe and are exonerated from classification as a carcinogen in accordance with EU Commission Directive 97/69/EC.

### **SECTION 12 ECOLOGICAL INFORMATION**

ENVIRONMENTAL TOXICITY: This product has no known adverse effect on the ecology. A large discharge directly into waterways would not be expected to kill aquatic life.

Ecotoxicity Values: Not determined.

### **SECTION 13** DISPOSAL CONSIDERATIONS

#### **WASTE DISPOSAL METHOD:**

#### A. General Product Information

Dispose material in accordance with local regulations. Contact the local agency for specific rules.

#### **B.** Component Exposure Limits

Dispose material in accordance with local regulations.

### **SECTION 14** TRANSPORT INFORMATION

Material not restricted for transportation regulations

Same as product name. **Shipping Name** 

**Hazard Class:** Not classified

UN/NA#: None. Not classified.

**Packing Group:** None

Label (s) Required: Not applicable. GGVSec/MDG-Code: Not classified. ICAO/IATA-DGR: Not applicable.

RID/ADR: None ADNR: None

### **SECTION 15** REGULATORY INFORMATION

#### A. General Product Information

Classification: The product is not classified as hazardous under Chemicals Hazardous Information and Packaging for Supply (CHIPS 2000).

The mineral wool in this product is exonerated from classification as a carcinogen according to Note Q in EU Commission Directive 97/69/EC.

MSDS No 026-11910-915

REV 02 - Date: August 10, 2012

## USG Middle East Ltd.

#### **B. Component Exposure Limits**

Recommended maximum exposure limit (MEL) is 1 fibre/cc (respirable) and/or 5 mg/m<sub>3</sub> (respirable dust), 8 hour TWA. Refer to current edition of HSE EH40 "Occupational Exposure Limits".

### SECTION 16 OTHER INFORMATION

These products should be used in accordance with the recommendations shown in USGME current technical literature. This Material Safety Data Sheet should not be considered a replacement for the users own workplace risk assessment, which is a requirement of The Control of Substances Hazardous to Health (COSHH) Regulations 2002.

#### For further information, contact:

Hisham A. Zayyad, Sales International Director OR Ziad Malek, Production Manager **USG Middle East Ltd** 7410 Al Kharj Road

Second Industrial City

Dammam 34326 - 4201, Kingdom of Saudi Arabia

Tel: +966 3 812 0995

#### **Additional Literature:**

More information about the health and safety of slag wool is given in the publication entitled Health & Safety Assessment & Recommended Work Practices for Slag Wool Fibers.

Also, additional information about "Health Aspects. Insulation Wool (Glass-, Stone, and Slag-wool)" can be obtained at the European Insulation Manufacturers Association (EURIMA, Av.-Louise 375, bte 4, B-1050 Brussels).

**END**